

bank's or savings association's current recorded investment amount (including any unpaid prior liens on the property) exceeds 10 percent of the bank's or savings association's total equity capital on its most recent report of condition. A national bank or Federal savings association need notify the OCC under this paragraph (d)(1) only once.

(2) The required notification must demonstrate that the additional expenditure is consistent with the conditions and limitations in paragraph (c) of this section.

(3) Unless informed otherwise, the national bank or Federal savings association may implement the proposed plan on the thirty-first day (or sooner, if notified by the OCC) following receipt by the OCC of the notification, subject to any conditions imposed by the OCC.

§ 34.87 [Removed]

- 15. Remove § 34.87.

PART 46—ANNUAL STRESS TEST

- 16. The authority citation for part 46 continues to read as follows:

Authority: 12 U.S.C. 93a; 1463(a)(2); 5365(i)(2); and 5412(b)(2)(B).

§ 46.6 [Amended]

- 17. Section 46.6 is amended in paragraph (a)(2), in the first sentence, by removing “or part 167, as applicable,” after “12 CFR part 3”.

PART 160—LENDING AND INVESTMENT

- 18. The authority for part 160 continues to read as follows:

Authority: 12 U.S.C. 1462a, 1463, 1464, 1467a, 1701j–3, 1828, 3803, 3806, 5412(b)(2)(B); 42 U.S.C. 4106.

§ 160.100 [Amended]

- 19. Section 160.100 is amended by removing “or 167.1, as applicable,”.
- 20. Section 160.101 is amended by revising footnote 2 in appendix A to § 160.101 to read as follows:

§ 160.101 Real estate lending standards.

* * * * *

² For the state member banks, the term “total capital” means “total risk-based capital” as defined in Appendix A to 12 CFR part 208. For insured state non-member banks, “total capital” refers to that term described in table I of Appendix A to 12 CFR part 325. For national banks and Federal savings associations, the term “total capital” is defined at 12 CFR 3.2.

§ 160.172 [Removed]

- 21. Remove § 160.172.

PART 161—DEFINITIONS FOR REGULATIONS AFFECTING ALL SAVINGS ASSOCIATIONS

- 22. The authority for part 161 continues to read as follows:

Authority: 12 U.S.C. 1462a, 1463, 1464, 1467a, 5412(b)(2)(B).

§ 161.55 [Amended]

- 23. Section 161.55 is amended in paragraph (c) by removing “or part 167, as applicable” after “12 CFR part 3”.

PART 163—SAVINGS ASSOCIATIONS—OPERATIONS

- 24. The authority for part 163 continues to read as follows:

Authority: 12 U.S.C. 1462a, 1463, 1464, 1467a, 1817, 1820, 1828, 1831o, 3806, 5101 *et seq.*, 5412(b)(2)(B); 31 U.S.C. 5318; 42 U.S.C. 4106.

§ 163.74 [Amended]

- 25. Section 163.74 is amended in paragraphs (i)(2)(iv) and (v) by removing “or part 167, as applicable,” after “12 CFR part 3”.

§ 163.80 [Amended]

- 26. Section 163.80 is amended in paragraph (e)(1) introductory text by removing “or part 167, as applicable”.

PART 167—[REMOVED]

- 27. Under the authority of 12 U.S.C. 1464, part 167 is removed.

Dated: October 11, 2019.

Morris R. Morgan,

First Deputy Comptroller, Comptroller of the Currency.

[FR Doc. 2019–22823 Filed 10–21–19; 8:45 am]

BILLING CODE 4810–33–P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA–2019–0580; Product Identifier 2019–NM–019–AD; Amendment 39–19765; AD 2019–20–12]

RIN 2120–AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Airbus SAS Model A330–243, –243F,

–341, –342, and –343 airplanes. This AD was prompted by a determination that cracks can develop on the ripple damper weld of the hydraulic pressure tube assembly and reports of failure of the ripple damper of the hydraulic pressure tube assembly. This AD requires replacement of the affected hydraulic pressure tube assembly or modification of both engines, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 26, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 26, 2019.

ADDRESSES: For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 1000; email ADs@easa.europa.eu; internet www.easa.europa.eu. You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0580.

Examining the AD Docket

You may examine the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0580; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3229.

SUPPLEMENTARY INFORMATION:

Discussion

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0031, dated February 13, 2019 (“EASA AD 2019–0031”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for all Airbus SAS Model A330–243, –243F, –341, –342, and –343 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to all Airbus SAS Model A330–243, –243F, –341, –342, and –343 airplanes. The NPRM published in the **Federal Register** on July 31, 2019 (84 FR 37162). The NPRM was prompted by a determination that cracks can develop on the ripple damper weld of the hydraulic pressure tube assembly and reports of failure of the ripple damper of the hydraulic pressure tube assembly. The NPRM proposed to require replacement of the affected hydraulic

pressure tube assembly or modification of both engines.

The FAA is issuing this AD to address cracking of the ripple damper weld of the hydraulic pressure tube assembly, which could lead to hydraulic fluid leakage and consequent loss of the green hydraulic system. This condition, if combined with other system failures, could result in reduced control of the airplane. See the MCAI for additional background information.

Comments

The FAA gave the public the opportunity to participate in developing this final rule. The FAA received no comments on the NPRM or on the determination of the cost to the public.

Conclusion

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

Related IBR Material Under 1 CFR Part 51

EASA AD 2019–0031 describes procedures for replacement of the affected hydraulic pressure tube assembly with a serviceable hydraulic pressure tube assembly or modification of both engines. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 53 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
4 work-hours × \$85 per hour = \$340	\$20,000	\$20,340	\$1,078,020

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has

delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a “significant regulatory action” under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

2019–20–12 Airbus SAS: Amendment 39–19765; Docket No. FAA–2019–0580; Product Identifier 2019–NM–019–AD.

(a) Effective Date

This AD is effective November 26, 2019.

(b) Affected ADs

This AD affects AD 2017–07–03, Amendment 39–18841 (82 FR 15985, March 31, 2017; corrected April 13, 2017 (82 FR 17749)) (“AD 2017–07–03”).

(c) Applicability

This AD applies to all Airbus SAS Model A330–243, –243F, –341, –342, and –343 airplanes, certificated in any category.

(d) Subject

Air Transport Association (ATA) of America Code 71, Powerplant.

(e) Reason

This AD was prompted by a determination that cracks can develop on the ripple damper weld of the hydraulic pressure tube assembly and reports of failure of the ripple damper of the hydraulic pressure tube assembly. The FAA is issuing this AD to address cracking of the ripple damper weld of the hydraulic pressure tube assembly, which could lead to hydraulic fluid leakage and consequent loss of the green hydraulic system. This condition, if combined with other system failures, could result in reduced control of the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0031, dated February 13, 2019 ("EASA AD 2019-0031").

(h) Exceptions to EASA AD 2019-0031

(1) For purposes of determining compliance with the requirements of this AD: Where EASA AD 2019-0031 refers to its effective date, this AD requires using the effective date of this AD.

(2) The "Remarks" section of EASA AD 2019-0031 does not apply to this AD.

(i) Terminating Action for AD 2017-07-03

Accomplishing the actions required by this AD terminates all requirements of AD 2017-07-03 for that airplane only.

(j) No Reporting Requirement

Although the service information referenced in EASA AD 2019-0031 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

(k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: 9-ANM-116-AMOC-REQUESTS@faa.gov. Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must

be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or Airbus SAS's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

(3) *Required for Compliance (RC)*: For any service information referenced in EASA AD 2019-0031 that contains RC procedures and tests: Except as required by paragraph (k)(2) of this AD, RC procedures and tests must be done to comply with this AD; any procedures or tests that are not identified as RC are recommended. Those procedures and tests that are not identified as RC may be deviated from using accepted methods in accordance with the operator's maintenance or inspection program without obtaining approval of an AMOC, provided the procedures and tests identified as RC can be done and the airplane can be put back in an airworthy condition. Any substitutions or changes to procedures or tests identified as RC require approval of an AMOC.

(l) Related Information

For more information about this AD, contact Vladimir Ulyanov, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206-231-3229.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0031, dated February 13, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0031, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email ADS@easa.europa.eu; Internet www.easa.europa.eu. You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0580.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fedreg.legal@nara.gov, or go to: <http://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on October 11, 2019.

Michael Kaszycki,

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2019-22956 Filed 10-21-19; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION**Federal Aviation Administration****14 CFR Part 39**

[Docket No. FAA-2019-0492; Product Identifier 2019-NM-045-AD; Amendment 39-19766; AD 2019-20-13]

RIN 2120-AA64

Airworthiness Directives; Airbus SAS Airplanes

AGENCY: Federal Aviation Administration (FAA), Department of Transportation (DOT).

ACTION: Final rule.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for certain Airbus SAS Model A330-200, A330-200 Freighter, and A330-300 series airplanes. This AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This AD requires revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective November 26, 2019.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of November 26, 2019.

ADDRESSES: For service information identified in this final rule, contact Airbus SAS, Airworthiness Office—EAL, Rond-Point Emile Dewoitine No: 2, 31700 Blagnac Cedex, France; telephone +33 5 61 93 36 96; fax +33 5 61 93 45 80; email airworthiness.A330-A340@airbus.com; internet <http://www.airbus.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <http://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0492.

Examining the AD Docket

You may examine the AD docket on the internet at <http://>