

amount during the fourth year of the transition period, and decrease amounts of DTAs arising from temporary differences by twenty-five percent of its DTA transitional amount during the fifth year of the transition period;

(C) Decrease amounts of AACL by one-hundred percent of its modified AACL transitional amount during the first year of the transition period, decrease amounts of AACL by one hundred percent of its modified AACL transitional amount during the second year of the transition period, decrease amounts of AACL by seventy-five percent of its modified AACL transitional amount during the third year of the transition period, decrease amounts of AACL by fifty percent of its AACL transitional amount during the fourth year of the transition period, and decrease amounts of AACL by twenty-five percent of its AACL transitional amount during the fifth year of the transition period; and

(D) Increase average total consolidated assets as reported on the Call Report for purposes of the leverage ratio by one-hundred percent of its modified CECL transitional amount during the first year of the transition period, increase average total consolidated assets as reported on the Call Report for purposes of the leverage ratio by one hundred percent of its modified CECL transitional amount during the second year of the transition period, increase average total consolidated assets as reported on the Call Report for purposes of the leverage ratio by seventy-five percent of its modified CECL transitional amount during the third year of the transition period, increase average total consolidated assets as reported on the Call Report for purposes of the leverage ratio by fifty percent of its modified CECL transitional amount during the fourth year of the transition period, and increase average total consolidated assets as reported on the Call Report for purposes of the leverage ratio by twenty-five percent of its modified CECL transitional amount during the fifth year of the transition period.

(ii) An advanced approaches FDIC-supervised institution that has made the election described in paragraph (a)(1) of this section in its first Call Report filed for the fiscal year that begins during the 2020 calendar year may make the following additional adjustments to its calculation of regulatory capital ratios:

(A) Increase total leverage exposure for purposes of the supplementary leverage ratio by one-hundred percent of its modified CECL transitional amount during the first year of the transition period, increase total leverage exposure for purposes of the supplementary

leverage ratio by one hundred percent of its modified CECL transitional amount during the second year of the transition period, increase total leverage exposure for purposes of the supplementary leverage ratio by seventy-five percent of its modified CECL transitional amount during the third year of the transition period, increase total leverage exposure for purposes of the supplementary leverage ratio by fifty percent of its CECL transitional amount during the fourth year of the transition period, and increase total leverage exposure for purposes of the supplementary leverage ratio by twenty-five percent of its CECL transitional amount during the fifth year of the transition period; and

(B) An advanced approaches FDIC-supervised institution that has completed the parallel run process and has received notification from the FDIC pursuant to § 324.121(d) must decrease amounts of eligible credit reserves by one-hundred percent of its eligible credit reserves transitional amount during the first year of the transition period, decrease amounts of eligible credit reserves by one hundred percent of its eligible credit reserves transitional amount during the second year of the transition period, decrease amounts of eligible credit reserves by seventy-five percent of its eligible credit reserves transitional amount during the third year of the transition period, decrease amounts of eligible credit reserves by fifty percent of its eligible credit reserves transitional amount during the fourth year of the transition period, and decrease amounts of eligible credit reserves by twenty-five percent of its eligible credit reserves transitional amount during the fifth year of the transition period.

(e) *Eligible credit reserves shortfall.* An advanced approaches FDIC-supervised institution that has completed the parallel run process and has received notification from the FDIC pursuant to § 324.121(d), whose amount of expected credit loss exceeded its eligible credit reserves immediately prior to the adoption of CECL, and that has an increase in common equity tier 1 capital as of the beginning of the fiscal year in which it adopts CECL after including the first year portion of the CECL transitional amount (or modified CECL transitional amount) must decrease its CECL transitional amount used in paragraph (c) of this section (or modified CECL transitional amount used in paragraph (d) of this section) by the full amount of its DTA transitional amount (or modified DTA transitional amount).

(f) *Business combinations.* Notwithstanding any other requirement

in this section, for purposes of this paragraph (f), in the event of a business combination involving an FDIC-supervised institution where one or both FDIC-supervised institutions have elected the treatment described in this section:

(1) If the acquirer FDIC-supervised institution (as determined under GAAP) elected the treatment described in this section, the acquirer FDIC-supervised institution must continue to use the transitional amounts (unaffected by the business combination) that it calculated as of the date that it adopted CECL through the end of its transition period.

(2) If the acquired insured depository institution (as determined under GAAP) elected the treatment described in this section, any transitional amount of the acquired insured depository institution does not transfer to the resulting FDIC-supervised institution.

Morris R. Morgan,

First Deputy Comptroller, Comptroller of the Currency.

By order of the Board of Governors of the Federal Reserve System.

Ann E. Misback,

Secretary of the Board.

Federal Deposit Insurance Corporation.

By order of the Board of Directors.

Dated at Washington, DC, on or about March 26, 2020.

Robert E. Feldman,

Executive Secretary.

[FR Doc. 2020-06770 Filed 3-30-20; 8:45 am]

BILLING CODE 4810-33-P; 6210-01-P; 6714-01-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2018-0538; Product Identifier 2012-NE-47-AD; Amendment 39-19885; AD 2020-06-16]

RIN 2120-AA64

Airworthiness Directives; Rolls-Royce, Deutschland Ltd. & Co. KG (Formerly Rolls-Royce plc) Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule.

SUMMARY: The FAA is superseding Airworthiness Directive (AD) AD 2017-03-02 for certain Rolls-Royce, Deutschland Ltd. & Co. KG RB211 Trent 768-60, 772-60, and 772B-60 model turbofan engines. AD 2017-03-02 required initial and repetitive ultrasonic inspections (UIs) of the affected low-pressure (LP) compressor blades. This

AD requires initial and repetitive UIs of the affected LP compressor blades and, depending on the results of the UIs, their replacement with a part eligible for installation. This AD was prompted by LP compressor blade partial airfoil release events. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective May 5, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of May 5, 2020.

ADDRESSES: For service information identified in this final rule, contact Rolls-Royce, Deutschland Ltd. & Co. KG, Eschenweg 11, 15827 Blankenfelde-Mahlow, Germany; phone: +49 (0) 33 708 6 0; email: <https://www.rolls-royce.com/contact-us.aspx>. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0538.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0538; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this AD, the mandatory continuing airworthiness information (MCAI), regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

FOR FURTHER INFORMATION CONTACT: Stephen Elwin, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7236; fax: 781-238-7199; email: Stephen.L.Elwin@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA issued a supplemental notice of proposed rulemaking (SNPRM) to amend 14 CFR part 39 to supersede AD 2017-03-02, Amendment 39-18793 (82 FR 10701, February 15, 2017), (“AD 2017-03-02”). AD 2017-03-02 applied to Rolls-Royce, Deutschland Ltd. & Co. KG (formerly Rolls-Royce plc) RB211 Trent 768-60, 772-60, and 772B-60

turbofan engines, with LP compressor blade, part number (P/N) FK23411, FK25441, FK25968, FW11901, FW15393, FW23643, FW23741, FW23744, KH23403, or KH23404, installed. The SNPRM published in the **Federal Register** on November 15, 2019 (84 FR 62482). The FAA preceded the SNPRM with an NPRM that published in the **Federal Register** on August 14, 2018 (83 FR 40161). The NPRM proposed to continue to require initial and repetitive UIs of the affected LP compressor blades at a reduced interval. The SNPRM proposed to require initial and repetitive UIs of the affected LP compressor blade and replacement of the LP compressor blade with a part eligible for installation if the LP compressor blade fails a UI. The FAA is issuing this AD to address the unsafe condition on these products.

The European Union Aviation Safety Agency (EASA), which is the Technical Agent for the Member States of the European Community, has issued EASA AD 2018-0188R1, dated September 5, 2018 (referred to after this as “the MCAI”), to address the unsafe condition on these products. The MCAI states:

Occurrences have been reported of LP compressor partial aerofoil blade release events on RR Trent 700 engines. While primary containment of the released sections was achieved in each case, some of the releases did exhibit secondary effects that are considered to present a potential hazard.

This condition, if not detected and corrected, could lead to LP compressor blade release with possible consequent loss of the engine nose cowl, under cowl fires and forward projection of secondary debris, possibly resulting in damage to the aeroplane and/or injury to persons on the ground.

To address this potential unsafe condition, RR published NMSB RB.211-72-G872, providing inspection instructions and, consequently, EASA issued AD 2012-0247 to require a one-time inspection of the higher life LP compressor blades. After identification of a population of these LP compressor blades that were incorrectly inspected, RR issued NMSB RB.211-72-H311 and, consequently, EASA issued AD 2013-0060, retaining the requirements of EASA AD 2012-0247, which was superseded, to require a one-time re-inspection of the affected blades.

After that AD was issued, to mitigate the risk of further partial LP compressor blade release events, RR issued NMSB RB.211-72-AH465, providing instructions for ultrasonic inspection of the affected parts to detect subsurface anomalies in the aerofoil. Consequently, EASA issued AD 2014-0031, superseding [EASA] AD 2013-0060, to require repetitive inspections of all affected LP compressor blades and, depending on findings, replacement.

Thereafter, EASA issued AD 2016-0141, retaining the requirements of [EASA] AD 2014-0031, which was superseded, to reduce

inspection threshold (RR Alert NMSB RB.211-72-AH465 Revision 2). Prompted by further analysis, EASA issued AD 2017-0241, retaining the requirements of EASA AD 2016-0141, which was superseded, further reducing the inspection threshold and interval (RR Alert NMSB RB.211-72-AH465 Revision 4).

Since EASA AD 2017-0241 was issued, RR issued the NMSB to distinguish between standard operations and NSO and to determine the applicable inspection threshold and interval. The flight cycles (FC) accumulated by operators conducting NSO have to be calculated using the beta factor shown in Table of the NMSB. The NMSB also introduces, for engines that have accumulated more than 600 FC or standard duty cycles (SDC, for engines used in NSO), a closing date by which these have to be inspected at least once.

For the reason described above, this [EASA] AD retains the requirements of EASA AD 2017-0241, which is superseded, and requires implementation of the changes introduced.

You may obtain further information by examining the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2018-0538.

Comments

The FAA gave the public the opportunity to participate in developing this AD. The following presents the comments received on the SNPRM and the FAA's response to each comment.

Request To Update Service Information

Rolls-Royce plc (RR), American Airlines (American), and Delta Air Lines (Delta) requested that RR Alert Non-Modification Service Bulletin (NMSB) RB.211-72-AH465, Revision 6, dated November 29, 2019 (“the NMSB”), be referenced in this AD instead of Revision 5 of the NMSB. Delta and American commented Revision 6 offers an optional water-coupled phased array inspection that provides a more reliable and repeatable technique and increases detection sensitivity to identify smaller defects. RR further commented that Revision 6 has been approved by the European Aviation Safety Agency.

The FAA agrees. RR published Revision 6 of the NMSB to allow an alternative water-coupled phased array inspection. Operators may still use the C-scan and gel-coupled phased array inspection techniques as specified in Revision 6, or earlier versions, of the NMSB.

Request To Allow Use of Later Versions of Service Information

Delta requested that this AD allow the use of later approved revisions of RR Alert NMSB RB.211-72-AH465. Delta

indicated that this is something that has been achieved before in other FAA ADs when an FAA AD incorporates by reference the EASA AD.

The FAA disagrees. As set forth in Title 1 of the Code of Federal Regulations, Section 51.1(f), incorporation by reference of a publication is limited to the edition of the publication that is approved. Future amendments or revisions of the publication are not included. Further, this AD does not incorporate by reference the EASA AD.

Support for the AD

The Air Line Pilots Association commented that it supports the AD as proposed.

Conclusion

The FAA reviewed the relevant data, considered the comments received, and determined that air safety and the public interest require adopting this AD with the change described previously.

Related Service Information Under 1 CFR Part 51

The FAA reviewed RR Alert NMSB RB.211-72-AH465, Revision 6, dated

November 29, 2019. The NMSB describes procedures for performing a UI of the LP compressor blades. This service information is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

Costs of Compliance

The FAA estimates that this AD affects 56 engines installed on airplanes of U.S. registry.

The FAA estimates the following costs to comply with this AD:

ESTIMATED COSTS

Action	Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Inspect LP compressor blade	44 work-hours × \$85 per hour = \$3,740	\$0	\$3,740	\$209,440

The FAA estimates the following costs to do any necessary replacements that would be required based on the

results of the inspection. The FAA has no way of determining the number of

engines that might need this replacement.

ON-CONDITION COSTS

Action	Labor cost	Parts cost	Cost per product
Replace LP compressor blade (one blade per 77 engine sets).	6 work-hours × \$85 per hour = \$510	\$103,000	\$103,510

According to the manufacturer, some of the costs of this AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all costs in our cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, Section 106, describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701, "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or

develop on products identified in this rulemaking action.

Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends part 39 of the Federal Aviation Regulations (14 CFR part 39) as follows:

PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

§ 39.13 [Amended]

- 2. The FAA amends § 39.13 by removing Airworthiness Directive (AD) 2017-03-02, Amendment 39-18793 (82 FR 10701, February 15, 2017), and adding the following new AD:

2020-06-16 Rolls-Royce, Deutschland Ltd. & Co. KG (formerly Rolls-Royce plc): Amendment 39-19885; Docket No. FAA-2018-0538; Product Identifier 2012-NE-47-AD.

(a) Effective Date

This AD is effective May 5, 2020.

(b) Affected ADs

This AD replaces AD 2017–03–02, Amendment 39–18793 (82 FR 10701, February 15, 2017).

(c) Applicability

This AD applies to Rolls-Royce Deutschland Ltd. & Co. KG (formerly Rolls-Royce plc) RB211 Trent 768–60, 772–60, and 772B–60 turbofan engines, with low-pressure (LP) compressor blade, part number (P/N) FK23411, FK25441, FK25968, FW11901, FW15393, FW23643, FW23741, FW23744, KH23403, or KH23404, installed.

(d) Subject

Joint Aircraft System Component (JASC) Code 7230, Turbine Engine Compressor Section.

(e) Unsafe Condition

This AD was prompted by LP compressor blade partial airfoil release events. While released sections were contained in each case, projection of secondary debris and effects could present a potential hazard. The FAA is issuing this AD to prevent LP compressor blade airfoil separation. The unsafe condition, if not addressed, could result in damage to the engine and damage to the airplane.

(f) Compliance

Comply with this AD within the compliance times specified, unless already done.

(g) Required Actions

(1) Within the compliance time specified in Figure 1 to paragraph (g)(1) of this AD and

thereafter, at intervals not to exceed 1,200 flight cycles (FCs) or Standard Duty Cycles (SDCs) for Non-Standard Operations (NSO), as applicable, since the last ultrasonic inspection (UI), perform a UI of each affected LP compressor blade in accordance with the Accomplishment Instructions, paragraph 3, of Rolls-Royce plc (RR) Alert Non-Modification Service Bulletin (NMSB) RB.211–72–AH465, Revision 6, dated November 29, 2019.

Note 1 to paragraph (g)(1): Paragraph 1.D of RR Alert NMSB RB.211–72–AH465, Revision 6, dated November 29, 2019, describes how to determine the applicable SDCs. The Time Limits Manual (TLM), 05–00–01, defines NSO.

Figure 1 to paragraph (g)(1) – Inspection Threshold

FCs/SDC Accumulated Since New or Since Last Inspection Required by paragraph (g)(1)	Compliance Times
Less than 1,100 FCs/SDCs	Before exceeding 1,200 FCs/SDCs since new.
1,100 FCs/SDCs or greater	Within 100 FCs/SDCs after the effective date of this AD, or before exceeding 2,400 FCs/SDCs since new, whichever occurs first.

(2) If, during any inspection required by paragraph (g)(1) of this AD, a LP compressor blade is rejected by the UI, as defined in Accomplishment Instructions, paragraph 3, of RR Alert NMSB RB.211–72–AH465, Revision 6, dated November 29, 2019, before further flight, or before returning the LP compressor blade to service, whichever occurs first, remove the affected LP compressor blade from service and replace with a part eligible for installation.

(h) Installation Prohibition

After the effective date of this AD, do not install an affected LP compressor blade on an engine unless the LP compressor blade meets the conditions specified in paragraphs (h)(1) or (2) of this AD, as applicable.

(1) The affected part has not exceeded 1,200 FC or SDCs (for NSO) since new, or since an inspection performed in accordance with either RR Alert NMSB RB.211–72–AH465, Revision 6, dated, November 29, 2019, or with any of the service information referenced in paragraph (j)(1) and (2) of this AD.

(2) Prior to installation, the affected part has passed an ultrasonic inspection in accordance with paragraph (g)(1) of this AD.

(i) No Reporting Requirement

The reporting requirements in the Accomplishment Instructions, paragraph 3 of RR Alert NMSB RB.211–72–AH465, Revision

6, dated November 29, 2019, are not required by this AD.

(j) Credit for Previous Actions

You may take credit for LP compressor blade UIs required by paragraph (g)(1) of this AD, if you performed the UI before the effective date of this AD using:

(1) For initial inspections: RR NMSB RB.211–72–G702, dated May 23, 2011; RR NMSB RB.211–72–G872, Revision 2, dated March 8, 2013, or earlier versions; RR NMSB RB.211–72–H311, dated March 8, 2013; RR NMSB RB.211–72–AH465, Revision 5, dated July 26, 2018, or earlier versions; RR Engine Manual E-Trent-1RR, Task 72–31–11–200–806; or Airbus A330 Aircraft Maintenance Manual (AMM) Task 72–31–41–270–801, or AMM Task 72–31–41–270–802.

(2) For repetitive inspections: The instructions referenced in the mandatory inspection paragraph of the applicable engine TLM, provided the compliance times of this AD are not exceeded.

(k) Alternative Methods of Compliance (AMOCs)

(1) The Manager, ECO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly

to the manager of the ECO Branch, send it to the attention of the person identified in paragraph (l)(1) of this AD. You may email your request to: ANE-AD-AMOC@faa.gov.

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(l) Related Information

(1) For more information about this AD, contact Stephen Elwin, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781–238–7236; fax: 781–238–7199; email: Stephen.L.Elwin@faa.gov.

(2) Refer to European Union Aviation Safety Agency (EASA) AD 2018–0188R1, dated September 5, 2018, for more information. You may examine the EASA AD in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating it in Docket No. FAA–2018–0538.

(m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Rolls-Royce plc (RR) Alert Non-Modification Service Bulletin RB.211-72-AH465, Revision 6, dated November 29, 2019.

(ii) [Reserved]

(3) For RR service information identified in this AD, contact Rolls-Royce Deutschland Ltd & Co KG, Eschenweg 11, 15827 Blankenfelde-Mahlow, Germany; phone: +49 (0) 33 708 6 0; email: <https://www.rolls-royce.com/contact-us.aspx>.

(4) You may view this service information at FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA, 01803. For information on the availability of this material at the FAA, call 781-238-7759.

(5) You may view this service information at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email: fedreg.legal@nara.gov, or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on March 26, 2020.

Gaetano A. Sciortino,

Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2020-06640 Filed 3-30-20; 8:45 am]

BILLING CODE 4910-13-P

DEPARTMENT OF TRANSPORTATION

Federal Aviation Administration

14 CFR Part 39

[Docket No. FAA-2020-0299; Project Identifier AD-2020-00247-E; Amendment 39-21106; AD 2020-07-02]

RIN 2120-AA64

Airworthiness Directives; Pratt & Whitney Turbofan Engines

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Final rule; request for comments.

SUMMARY: The FAA is adopting a new airworthiness directive (AD) for all Pratt & Whitney (PW) PW1519G, PW1521G, PW1521G-3, PW1521GA, PW1524G, PW1524G-3, PW1525G, and PW1525G-3 model turbofan engines. This AD requires the removal from service of certain electronic engine control (EEC) full authority digital electronic control (FADEC) software and the installation of a software version eligible for installation. This AD was prompted by reports of four in-flight shutdowns (IFSDs) due to failure of the low-pressure compressor (LPC) rotor 1 (R1) and by subsequent findings of cracked LPC R1s during inspections. The FAA is issuing this AD to address the unsafe condition on these products.

DATES: This AD is effective April 15, 2020.

The FAA must receive comments on this AD by May 15, 2020.

ADDRESSES: You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- **Federal eRulemaking Portal:** Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- **Fax:** 202-493-2251.

- **Mail:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- **Hand Delivery:** U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Pratt & Whitney, 400 Main Street, East Hartford, CT 06118; phone: 800-565-0140; fax: 860-565-5442; email: help24@pw.utc.com; internet: <https://fleetcare.pw.utc.com>. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759.

Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2020-0299; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, any comments received, and other information. The street address for the Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

FOR FURTHER INFORMATION CONTACT:

Kevin M. Clark, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA, 01803; phone: 781-238-7088; fax: 781-238-7199; email: kevin.m.clark@faa.gov.

SUPPLEMENTARY INFORMATION:

Discussion

The FAA has received reports of four instances of IFSDs occurring on the affected model turbofan engines since 2019.

In response to the two IFSDs that occurred in July and September 2019, and in response to on-going investigations of these IFSDs, the FAA

issued AD 2019-19-11 (84 FR 50719, September 26, 2019), to perform inspections of the LPC R1 to prevent failures. The FAA subsequently superseded AD 2019-19-11, issuing AD 2019-21-11 (84 FR 57813, October 29, 2019) in response to another IFSD and to expand the population of affected engines that needed inspection of the LPC R1. Since the effective date of AD 2019-21-11, another IFSD occurred in February 2020. Analysis by the manufacturer determined that the LPC vane schedules were putting the engine in a condition to experience an acoustic resonance that damages the LPC R1, which then leads to LPC R1 failure. In response, the manufacturer updated the EEC FADEC software to improve vane scheduling to avoid acoustic resonance.

This condition, if not addressed, could result in uncontained release of the LPC R1, damage to the engine, and damage to the airplane. The FAA is issuing this AD to address the unsafe condition on these products.

Related Service Information

The FAA reviewed PW Service Bulletin (SB) PW1000G-A-73-00-0036-00A-930A-D, Issue No. 002, dated March 4, 2020, and PW SB PW1000G-A-73-00-0041-00A-930A-D, Issue No.001, dated March 4, 2020. These SBs describe procedures for replacing or modifying the EEC FADEC software.

FAA's Determination

The FAA is issuing this AD because it evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

AD Requirements

This AD requires the removal from service of certain EEC FADEC software and the installation of a software version eligible for installation.

Interim Action

The FAA considers this AD interim action. The root cause of the LPC R1 failures is still being investigated and the FAA will consider further rulemaking depending on the results of the investigation.

Justification for Immediate Adoption and Determination of the Effective Date

Section 553(b)(3)(B) of the Administrative Procedure Act (APA) (5 U.S.C.) authorizes agencies to dispense with notice and comment procedures for rules when the agency, for "good cause," finds that those procedures are "impracticable, unnecessary, or contrary