

to submit certain information to the manufacturer, this AD does not include that requirement.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs)*: The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer*: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or ATR—GIE Avions de Transport Régional's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

#### (k) Related Information

(1) For information about EASA AD 2019–0278, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; telephone +49 221 89990 6017; email [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–1075.

(2) For more information about this AD, contact Sharam Daneshmandi, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3220; email [shahram.daneshmandi@faa.gov](mailto:shahram.daneshmandi@faa.gov).

Issued on January 7, 2020.

**Michael Kaszycki,**

Acting Director, System Oversight Division, Aircraft Certification Service.

[FR Doc. 2020–00446 Filed 1–16–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2019–1074; Product Identifier 2019–NM–191–AD]

RIN 2120–AA64

#### Airworthiness Directives; Embraer S.A. Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for certain Embraer S.A. Model ERJ 170 airplanes and Model ERJ 190–100 STD, –100 LR, –100 ECJ, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes. This proposed AD was prompted by a determination that certain main landing gear (MLG) aft pintle pins repaired using a sulphamate nickel plating have a life limit that is less than the certified life limit. This proposed AD would require a one-time records review and a general visual inspection (GVI) of the MLG aft pintle pins to determine if certain repairs were done, and replacement of certain MLG aft pintle pins with serviceable MLG aft pintle pins, as specified in an Agência Nacional de Aviação Civil (ANAC) Brazilian AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by March 2, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202–493–2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

- *Hand Delivery:* Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For the material identified in this proposed AD that will be incorporated by reference (IBR), contact National Civil Aviation Agency, Aeronautical Products Certification Branch (GGCP), Rua Laurent Martins, n°209, Jardim Esplanada, CEP 12242–431—São José dos Campos—SP, Brazil; telephone 55

(12) 3203–6600; email [pac@anac.gov.br](mailto:pac@anac.gov.br); internet [www.anac.gov.br/en/](http://www.anac.gov.br/en/). You may find this IBR material on the ANAC website at <https://sistemas.anac.gov.br/certificacao/DA/DAE.asp>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–1074.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–1074; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

#### FOR FURTHER INFORMATION CONTACT:

Krista Greer, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3221; email [krista.greer@faa.gov](mailto:krista.greer@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Comments Invited

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under the **ADDRESSES** section. Include “Docket No. FAA–2019–1074; Product Identifier 2019–NM–191–AD” at the beginning of your comments. The FAA specifically invite comments on the overall regulatory, economic, environmental, and energy aspects of this NPRM. The FAA will consider all comments received by the closing date and may amend this NPRM based on those comments.

The FAA will post all comments received, without change, to <https://www.regulations.gov>, including any personal information you provide. The FAA will also post a report summarizing each substantive verbal contact received about this NPRM.

#### Discussion

The ANAC, which is the aviation authority for Brazil, has issued Brazilian AD 2019–11–07, effective November 18, 2019 (“Brazilian AD 2019–11–07”) (also

referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain Embraer S.A. Model ERJ 170–100 LR, –100 STD, –100 SE, and –100 SU airplanes; Model ERJ 170–200 LR, –200 SU, –200 STD, and –200 LL airplanes; and Model ERJ 190–100 STD, –100 LR, –100 ECJ, –100 IGW, –100 SR, –200 STD, –200 LR, and –200 IGW airplanes. Model ERJ 190–100 SR airplanes are not certified by the FAA and are not included on the U.S. type certificate data sheet; this AD, therefore, does not include those airplanes in the applicability.

This proposed AD was prompted by a determination that certain MLG aft pintle pins repaired using a sulphamate nickel plating have a life limit that is less than the certified life limit. The FAA is proposing this AD to address failure of the affected MLG aft pintle pins before reaching the certified life limit, which could result in collapse of the MLG during takeoff or landing. See the MCAI for additional background information.

Related IBR Material Under 1 CFR Part 51

Brazilian AD 2019–11–07 describes procedures for a one-time records review (for documentation of certain repairs) and a GVI of the MLG aft pintle pins to determine if certain repairs were done (by checking for certain markings

and part numbers), and replacement of certain MLG aft pintle pins with serviceable MLG aft pintle pins.

This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the ADDRESSES section.

FAA’s Determination and Requirements of This Proposed AD

This product has been approved by the aviation authority of another country, and is approved for operation in the United States. Pursuant to a bilateral agreement with the State of Design Authority, the FAA has been notified of the unsafe condition described in the MCAI referenced above. The FAA is proposing this AD because the agency evaluated all the relevant information and determined the unsafe condition described previously is likely to exist or develop in other products of the same type design.

Proposed AD Requirements

This proposed AD would require accomplishing the actions specified in Brazilian AD 2019–11–07 described previously, as incorporated by reference, except for any differences identified as exceptions in the regulatory text of this AD.

Explanation of Required Compliance Information

In the FAA’s ongoing efforts to improve the efficiency of the AD process, the FAA initially worked with Airbus and the European Union Aviation Safety Agency (EASA) to develop a process to use certain EASA ADs as the primary source of information for compliance with requirements for corresponding FAA ADs. The FAA has since coordinated with other manufacturers and civil aviation authorities (CAAs) to use this process. As a result, Brazilian AD 2019–11–07 will be incorporated by reference in the FAA final rule. This proposed AD would, therefore, require compliance with Brazilian AD 2019–11–07 in its entirety, through that incorporation, except for any differences identified as exceptions in the regulatory text of this proposed AD. Service information specified in Brazilian AD 2019–11–07 that is required for compliance with Brazilian AD 2019–11–07 will be available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–1074 after the FAA final rule is published.

Costs of Compliance

The FAA estimates that this proposed AD affects 659 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

ESTIMATED COSTS FOR REQUIRED ACTIONS

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
2 work-hours × \$85 per hour = \$170 .....	*\$	*\$170	*\$112,030

\* The FAA has received no definitive data that would enable the agency to provide parts cost estimates for the replacements specified in this proposed AD.

According to the manufacturer, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected individuals. The FAA does not control warranty coverage for affected individuals. As a result, the FAA has included all known costs in the cost estimate.

Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA’s authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency’s authority.

The FAA is issuing this rulemaking under the authority described in

Subtitle VII, Part A, Subpart III, Section 44701: “General requirements.” Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This proposed AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance

and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

Regulatory Findings

The FAA has determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

(1) Is not a “significant regulatory action” under Executive Order 12866,  
(2) Will not affect intrastate aviation in Alaska, and  
(3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### The Proposed Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

■ 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

■ 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**Embraer S.A.:** Docket No. FAA–2019–1074; Product Identifier 2019–NM–191–AD.

##### (a) Comments Due Date

The FAA must receive comments by March 2, 2020.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to the Embraer S.A. airplanes identified in paragraphs (c)(1) through (3), of this AD, certificated in any category, as identified in Agência Nacional de Aviação Civil (ANAC) Brazilian AD 2019–11–07, effective November 18, 2019 (“Brazilian AD 2019–11–07”).

(1) Model ERJ 170–100 LR, –100 STD, –100 SE, and –100 SU airplanes.

(2) Model ERJ 170–200 LR, –200 SU, –200 STD, and –200 LL airplanes.

(3) Model ERJ 190–100 STD, –100 LR, –100 ECJ, –100 IGW, –200 STD, –200 LR, and –200 IGW airplanes.

##### (d) Subject

Air Transport Association (ATA) of America Code 32, Landing gear.

##### (e) Reason

This AD was prompted by a determination that certain main landing gear (MLG) aft pintle pins repaired using a sulphamate nickel plating have a life limit that is less than the certified life limit. The FAA is issuing this AD to address failure of the affected MLG aft pintle pins before reaching the certified life limit, which could result in collapse of the MLG during takeoff or landing.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, Brazilian AD 2019–11–07.

#### (h) Exceptions to Brazilian AD 2019–11–07

(1) Where Brazilian AD 2019–11–07 refers to its effective date, this AD requires using the effective date of this AD.

(2) The “Alternative method of compliance (AMOC)” section of Brazilian AD 2019–11–07 does not apply to this AD.

(3) Where paragraphs (b)(1) through (3) of Brazilian AD 2019–11–07 specify to carry out an inspection in the airplane technical document documentation and a general visual inspection (GVI) on them, this AD requires a one-time records review and a general visual inspection (GVI) of the MLG aft pintle pins to determine if certain repairs were done.

(4) Where paragraphs (b)(1) through (3) of Brazilian AD 2019–11–07 specify to use a “new serviceable one,” for this AD, use a serviceable MLG aft pintle pin as defined in Brazilian AD 2019–11–07.

#### (i) No Requirement for Return of Parts

Although the service information referenced in Brazilian AD 2019–11–07 specifies to return parts to the manufacturer, this AD does not include that requirement.

#### (j) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (k)(2) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or ANAC; or ANAC’s authorized Designee. If approved by the ANAC Designee, the approval must include the Designee’s authorized signature.

#### (k) Related Information

(1) For information about Brazilian AD 2019–11–07, contact National Civil Aviation Agency, Aeronautical Products Certification Branch (GGCP), Rua Laurent Martins, n° 209,

Jardim Esplanada, CEP 12242–431—São José dos Campos—SP, Brazil; telephone 55 (12) 3203–6600; email [pac@anac.gov.br](mailto:pac@anac.gov.br); internet [www.anac.gov.br/en/](http://www.anac.gov.br/en/). You may find this ANAC AD on the ANAC website at <https://sistemas.anac.gov.br/certificacao/DA/DAE.asp>. You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–1074.

(2) For more information about this AD, contact Krista Greer, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; telephone and fax 206–231–3221; email [krista.greer@faa.gov](mailto:krista.greer@faa.gov).

Issued on January 7, 2020.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2020–00447 Filed 1–16–20; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2019–1073; Product Identifier 2019–NM–186–AD]

RIN 2120–AA64

#### Airworthiness Directives; Saab AB, Support and Services (Formerly Known as Saab AB, Saab Aeronautics) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

**SUMMARY:** The FAA proposes to adopt a new airworthiness directive (AD) for all Saab AB, Support and Services Model SAAB 2000 airplanes. This proposed AD was prompted by a determination that new or more restrictive airworthiness limitations are necessary. This proposed AD would require revising the existing maintenance or inspection program, as applicable, to incorporate new or more restrictive airworthiness limitations, as specified in a European Union Aviation Safety Agency (EASA) AD, which will be incorporated by reference. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by March 2, 2020.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR