

(3) Model 767–200, –300, –300F, and –400ER series airplanes, as identified in Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018.

#### (d) Subject

Air Transport Association (ATA) of America Code 34, Navigation.

#### (e) Unsafe Condition

This AD was prompted by reports of nuisance stick shaker activation while the airplane accelerated to cruise speed at the top of climb. This AD was also prompted by an investigation of those reports that revealed that the angle of attack (AOA) (also known as angle of airflow) sensor vanes could not prevent the build-up of ice, causing the AOA sensor vanes to become immobilized, which resulted in nuisance stick shaker activation. The FAA is issuing this AD to address ice build-up in the AOA sensor faceplate and vane, which may immobilize the AOA sensor vanes, and could result in inaccurate or unreliable AOA sensor data being transmitted to airplane systems and consequent loss of controllability of the airplane.

#### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

#### (g) Required Actions

Except as specified in paragraph (h) of this AD: Within 36 months after the effective date of this AD or at the applicable times specified in paragraph 1.E., “Compliance,” of Boeing Alert Service Bulletin 727–34A0247, Revision 1, dated October 1, 2019; Boeing Alert Service Bulletin 757–34A0611, Revision 1, dated March 22, 2019; or Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018; as applicable, whichever occurs first, do all applicable actions identified as “RC” (required for compliance) in, and in accordance with, the Accomplishment Instructions of Boeing Alert Service Bulletin 727–34A0247, Revision 1, dated October 1, 2019; Boeing Alert Service Bulletin 757–34A0611, Revision 1, dated March 22, 2019; or Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018; as applicable. All replacements of the affected AOA sensors must be done before further flight.

#### (h) Exceptions to Service Information Specifications

(1) Where Boeing Alert Service Bulletin 727–34A0247, Revision 1, dated October 1, 2019; Boeing Alert Service Bulletin 757–34A0611, Revision 1, dated March 22, 2019; or Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018; as applicable, uses the phrase “the original issue date of this service bulletin,” this AD requires using “the effective date of this AD.”

(2) Where Boeing Alert Service Bulletin 727–34A0247, Revision 1, dated October 1, 2019; Boeing Alert Service Bulletin 757–34A0611, Revision 1, dated March 22, 2019; or Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018; specify to accomplish a general visual inspection of the AOA sensors and to replace affected AOA

sensors, a review of the airplane maintenance records is acceptable in lieu of those actions if the part number of the installed AOA sensors can be conclusively determined during that review to have a new or serviceable AOA sensor part number identified in Boeing Alert Service Bulletin 727–34A0247, Revision 1, dated October 1, 2019; Boeing Alert Service Bulletin 757–34A0611, Revision 1, dated March 22, 2019; or Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018; as applicable.

#### (i) Credit for Previous Actions

This paragraph provides credit for actions specified in paragraph (g) of this AD, if those actions were performed before the effective date of this AD using Boeing Alert Service Bulletin 727–34A0247, dated January 2, 2019.

#### (j) Alternative Methods of Compliance (AMOCs)

(1) The Manager, Los Angeles ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (k) of this AD. Information may be emailed to: [9-ANM-LAACO-AMOC-Requests@faa.gov](mailto:9-ANM-LAACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Los Angeles ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

(4) For service information that contains steps that are labeled as Required for Compliance (RC), the provisions of paragraphs (j)(4)(i) and (ii) of this AD apply.

(i) The steps labeled as RC, including substeps under an RC step and any figures identified in an RC step, must be done to comply with the AD. If a step or substep is labeled “RC Exempt,” then the RC requirement is removed from that step or substep. An AMOC is required for any deviations to RC steps, including substeps and identified figures.

(ii) Steps not labeled as RC may be deviated from using accepted methods in accordance with the operator’s maintenance or inspection program without obtaining approval of an AMOC, provided the RC steps, including substeps and identified figures, can still be done as specified, and the airplane can be put back in an airworthy condition.

#### (k) Related Information

For more information about this AD, contact Jeffrey W. Palmer, Aerospace Engineer, Systems and Equipment Section, FAA, Los Angeles ACO Branch, 3960 Paramount Boulevard, Lakewood, CA 90712–4137; phone: 562–627–5351; fax: 562–627–5210; email: [Jeffrey.W.Palmer@faa.gov](mailto:Jeffrey.W.Palmer@faa.gov).

#### (l) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Service Bulletin 727–34A0247, Revision 1, dated October 1, 2019.

(ii) Boeing Alert Service Bulletin 757–34A0611, Revision 1, dated March 22, 2019.

(iii) Boeing Alert Service Bulletin 767–34A0828, dated December 6, 2018.

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on December 9, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division, Aircraft Certification Service.*

[FR Doc. 2019–27887 Filed 12–27–19; 8:45 am]

**BILLING CODE 4910–13–P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA–2019–0674; Product Identifier 2019–NM–079–AD; Amendment 39–21003; AD 2019–24–14]

RIN 2120–AA64

**Airworthiness Directives; 328 Support Services GmbH (Type Certificate Previously Held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain 328 Support Services GmbH Model 328–100 airplanes. This AD was prompted by a report of missing rivets on landing flap support arm 2. This AD requires an inspection of the landing flap support arms for missing rivets and corrective actions if necessary, as specified in a European Union Aviation Safety Agency (EASA) AD, which is incorporated by reference. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective February 3, 2020.

The Director of the Federal Register approved the incorporation by reference of a certain publication listed in this AD as of February 3, 2020.

**ADDRESSES:** For the material incorporated by reference (IBR) in this AD, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 1000; email: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu); internet: [www.easa.europa.eu](http://www.easa.europa.eu). You may find this IBR material on the EASA website at <https://ad.easa.europa.eu>. You may view this IBR material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195. It is also available in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0674.

**Examining the AD Docket**

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA–2019–0674; or in person at Docket Operations

between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M–30, West Building Ground Floor, Room W12–140, 1200 New Jersey Avenue SE, Washington, DC 20590.

**FOR FURTHER INFORMATION CONTACT:**

Todd Thompson, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3228.

**SUPPLEMENTARY INFORMATION:****Discussion**

The EASA, which is the Technical Agent for the Member States of the European Union, has issued EASA AD 2019–0096, dated April 30, 2019 (“EASA AD 2019–0096”) (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain 328 Support Services GmbH Model 328–100 airplanes.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would apply to certain 328 Support Services GmbH Model 328–100 airplanes. The NPRM published in the **Federal Register** on September 9, 2019 (84 FR 47173). The NPRM was prompted by a report of missing rivets on landing flap support arm 2. The NPRM proposed to require an inspection of the landing flap support arms for missing rivets and corrective actions if necessary.

The FAA is issuing this AD to address missing rivets, which could lead to the loss of one of two load paths, reducing the fatigue life of the affected flap arms and leading to fatigue cracking of the

support arms of the flaps, which could result in reduced structural integrity of the airplane. See the MCAI for additional background information.

**Comments**

The FAA gave the public the opportunity to participate in developing this final rule. The agency received no comments on the NPRM or on the determination of the cost to the public.

**Conclusion**

The FAA reviewed the relevant data and determined that air safety and the public interest require adopting this final rule as proposed, except for minor editorial changes. The FAA has determined that these minor changes:

- Are consistent with the intent that was proposed in the NPRM for addressing the unsafe condition; and
- Do not add any additional burden upon the public than was already proposed in the NPRM.

**Related IBR Material Under 1 CFR Part 51**

EASA AD 2019–0096 describes procedures for an inspection of the landing flap support arms for missing rivets, which includes a special detailed inspection (eddy current) of the landing flap support 2 arm along the edges and around the rivets for cracks, and corrective actions. Corrective actions include installing rivets and repairing cracks. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in the **ADDRESSES** section.

**Costs of Compliance**

The FAA estimates that this AD affects 22 airplanes of U.S. registry. The FAA estimates the following costs to comply with this AD:

**ESTIMATED COSTS FOR REQUIRED ACTIONS**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
6 work-hours × \$85 per hour = \$510 .....	\$0	\$510	\$11,220

The FAA estimates the following costs to do any necessary on-condition installation that would be required

based on the results of any required actions. The FAA has no way of determining the number of aircraft that

might need this on-condition installation:

**ESTIMATED COSTS OF ON-CONDITION INSTALLATION**

Labor cost	Parts cost	Cost per product
4 work-hours × \$85 per hour = \$340 .....	\$27	\$367

The FAA has received no definitive data that would enable the FAA to provide cost estimates for the on-condition crack repairs specified in this AD.

#### Authority for This Rulemaking

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: "General requirements." Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

This AD is issued in accordance with authority delegated by the Executive Director, Aircraft Certification Service, as authorized by FAA Order 8000.51C. In accordance with that order, issuance of ADs is normally a function of the Compliance and Airworthiness Division, but during this transition period, the Executive Director has delegated the authority to issue ADs applicable to transport category airplanes and associated appliances to the Director of the System Oversight Division.

#### Regulatory Findings

This AD will not have federalism implications under Executive Order 13132. This AD will not have a substantial direct effect on the States, on the relationship between the national government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify that this AD:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Will not affect intrastate aviation in Alaska, and
- (3) Will not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

#### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

#### Adoption of the Amendment

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

#### PART 39—AIRWORTHINESS DIRECTIVES

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

##### § 39.13 [Amended]

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2019-24-14 328 Support Services GmbH (Type Certificate previously held by AvCraft Aerospace GmbH; Fairchild Dornier GmbH; Dornier Luftfahrt GmbH):** Amendment 39-21003; Docket No. FAA-2019-0674; Product Identifier 2019-NM-079-AD.

##### (a) Effective Date

This AD is effective February 3, 2020.

##### (b) Affected ADs

None.

##### (c) Applicability

This AD applies to 328 Support Services GmbH Model 328-100 airplanes, certificated in any category, serial numbers 3032 through 3063 inclusive.

##### (d) Subject

Air Transport Association (ATA) of America Code 57, Wings.

##### (e) Reason

This AD was prompted by a report of missing rivets on landing flap support arm 2. The FAA is issuing this AD to address missing rivets, which could lead to the loss of one of two load paths, reducing the fatigue life of the affected flap arms and leading to fatigue cracking of the support arms of the flaps, which could result in reduced structural integrity of the airplane.

##### (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

##### (g) Requirements

Except as specified in paragraph (h) of this AD: Comply with all required actions and compliance times specified in, and in accordance with, European Union Aviation Safety Agency (EASA) AD 2019-0096, dated April 30, 2019 ("EASA AD 2019-0096").

##### (h) Exceptions to EASA AD 2019-0096

- (1) Where EASA AD 2019-0096 refers to its effective date, this AD requires using the effective date of this AD.

- (2) The "Remarks" section of EASA AD 2019-0096 does not apply to this AD.

##### (i) Corrective Action for Cracking

If any crack is found during any inspection required by paragraph (2) of EASA AD 2019-0096: Before further flight, repair using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or the EASA; or 328 Support Services GmbH's EASA Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

##### (j) No Reporting Requirement

Although the service information referenced in EASA AD 2019-0096 specifies to submit certain information to the manufacturer, this AD does not include that requirement.

##### (k) Other FAA AD Provisions

The following provisions also apply to this AD:

(1) *Alternative Methods of Compliance (AMOCs):* The Manager, International Section, Transport Standards Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the International Section, send it to the attention of the person identified in paragraph (l) of this AD. Information may be emailed to: [9-ANM-116-AMOC-REQUESTS@faa.gov](mailto:9-ANM-116-AMOC-REQUESTS@faa.gov). Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(2) *Contacting the Manufacturer:* For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, International Section, Transport Standards Branch, FAA; or EASA; or 328 Support Services GmbH's EASA DOA. If approved by the DOA, the approval must include the DOA-authorized signature.

##### (l) Related Information

For more information about this AD, contact Todd Thompson, Aerospace Engineer, International Section, Transport Standards Branch, FAA, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206-231-3228.

##### (m) Material Incorporated by Reference

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.

(i) European Union Aviation Safety Agency (EASA) AD 2019-0096, dated April 30, 2019.

(ii) [Reserved]

(3) For information about EASA AD 2019-0096, contact the EASA, Konrad-Adenauer-Ufer 3, 50668 Cologne, Germany; phone: +49 221 89990 6017; email: [ADs@easa.europa.eu](mailto:ADs@easa.europa.eu);

internet: [www.easa.europa.eu](http://www.easa.europa.eu). You may find this EASA AD on the EASA website at <https://ad.easa.europa.eu>.

(4) You may view this material at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. This material may be found in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0674.

(5) You may view this material that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued in Des Moines, Washington, on December 9, 2019.

**Michael Kaszycki,**

*Acting Director, System Oversight Division,  
Aircraft Certification Service.*

[FR Doc. 2019-28067 Filed 12-27-19; 8:45 am]

**BILLING CODE 4910-13-P**

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0675; Product Identifier 2019-NM-068-AD; Amendment 39-19815; AD 2019-24-12]

**RIN 2120-AA64**

#### **Airworthiness Directives; De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by Bombardier, Inc.) Airplanes**

**AGENCY:** Federal Aviation Administration (FAA), Department of Transportation (DOT).

**ACTION:** Final rule.

**SUMMARY:** The FAA is adopting a new airworthiness directive (AD) for certain De Havilland Aircraft of Canada Limited Model DHC-8-401 and -402 airplanes. This AD was prompted by a report that certain fuselages were delivered with nonconforming keel tension fittings and stringer end fittings. This AD requires a detailed visual inspection of stringer end fittings and keel fittings for loose or working fasteners, signs of wear, and corrosion, and repair if necessary; and a general visual inspection of the keel tension fitting and stringer end fittings, as applicable, and repairs and replacement of the keel and stringer end fittings if necessary. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective February 3, 2020.

The Director of the Federal Register approved the incorporation by reference

of certain publications listed in this AD as of February 3, 2020.

**ADDRESSES:** For Bombardier, Inc., or De Havilland Aircraft of Canada Limited service information identified in this final rule, contact De Havilland Aircraft of Canada Limited, Q-Series Technical Help Desk, 123 Garratt Boulevard, Toronto, Ontario M3K 1Y5, Canada; phone: 416-375-4000; fax: 416-375-4539; email: [thd@dehavilland.com](mailto:thd@dehavilland.com); internet: <https://dehavilland.com>. You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206-231-3195. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0675.

#### **Examining the AD Docket**

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0675; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The address for Docket Operations is U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.

#### **FOR FURTHER INFORMATION CONTACT:**

Andrea Jimenez, Aerospace Engineer, Airframe and Propulsion Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; phone: 516-228-7330; fax: 516-794-5531; email: [9-avs-nyaco-cos@faa.gov](mailto:9-avs-nyaco-cos@faa.gov).

#### **SUPPLEMENTARY INFORMATION:**

##### **Discussion**

Transport Canada Civil Aviation (TCCA), which is the aviation authority for Canada, has issued Canadian AD CF-2019-06, dated February 18, 2019 (also referred to as the Mandatory Continuing Airworthiness Information, or “the MCAI”), to correct an unsafe condition for certain De Havilland Aircraft of Canada Limited Model DHC-8-401 and -402 airplanes. You may examine the MCAI in the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0675.

The FAA issued a notice of proposed rulemaking (NPRM) to amend 14 CFR part 39 by adding an AD that would

apply to certain Bombardier, Inc., Model DHC-8-401 and -402 airplanes. The NPRM published in the **Federal Register** on September 9, 2019 (84 FR 47170). The NPRM was prompted by a report that certain fuselages were delivered with non-conforming keel tension fittings and stringer end fittings. The NPRM proposed to require a detailed visual inspection of stringer end fittings and keel fittings for loose or working fasteners, signs of wear, and corrosion, and repair if necessary; and a general visual inspection of the keel tension fitting and stringer end fittings, as applicable, and repairs and replacement of the keel and stringer end fittings if necessary. The FAA is issuing this AD to address non-conforming keel tension fittings and stringer end fittings, which could lead to premature cracking and corrosion in several locations and compromise the structural integrity of the fuselage joints. See the MCAI for additional background information.

#### **Comments**

The FAA gave the public the opportunity to participate in developing this final rule. The following presents the comments received on the NPRM and the FAA's response to each comment.

#### **Request To Update the Design Approval Holder (DAH) for the Affected Airplanes**

Horizon Air requested that the FAA update the DAH for the affected airplanes. Horizon Air pointed out that De Havilland Aircraft of Canada Limited is now the DAH for the Model DHC-8-401 and -402 airplanes.

The FAA agrees with the commenter for the reasons provided and has updated this final rule accordingly.

#### **Request To Include Revised Service Information and Credit for Previous Revision**

Horizon Air requested that the FAA update the final rule to include revised service information. Horizon Air mentioned that De Havilland Aircraft of Canada Limited has issued Service Bulletin 84-53-75, Revision A, dated August 2, 2019. Horizon Air also requested that the FAA give credit for accomplishment of the required actions prior to the effective date of this AD using Bombardier Service Bulletin 84-53-75, dated August 29, 2018.

The FAA agrees with the commenter for the reasons provided and has updated this final rule to refer to De Havilland Aircraft of Canada Limited Service Bulletin 84-53-75, Revision A, dated August 2, 2019. The FAA has determined that no additional work is