

# Rules and Regulations

Federal Register

Vol. 84, No. 209

Tuesday, October 29, 2019

This section of the FEDERAL REGISTER contains regulatory documents having general applicability and legal effect, most of which are keyed to and codified in the Code of Federal Regulations, which is published under 50 titles pursuant to 44 U.S.C. 1510.

The Code of Federal Regulations is sold by the Superintendent of Documents.

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 13 and 406

#### Office of the Secretary

#### 14 CFR Part 383

#### Saint Lawrence Seaway Development Corporation

#### 33 CFR Part 401

#### Maritime Administration

#### 46 CFR Parts 221, 307, 340, and 356

#### Pipeline and Hazardous Materials Safety Administration

#### 49 CFR Parts 107, 171, and 190

#### Federal Railroad Administration

#### 49 CFR Parts 209, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 270, and 272

#### Federal Motor Carrier Safety Administration

#### 49 CFR Part 386

#### National Highway Traffic Safety Administration

#### 49 CFR Part 578

#### RIN 2105-AE80

#### Revisions to Civil Penalty Amounts

#### Correction

In rule document 2019-14101 beginning on page 37059 in the issue of Wednesday, July 31, 2019, make the following correction:

#### § 222.11 [Amended]

■ On page 37073, in the second column, amendatory instruction 47c should read as follows:

c. Remove the dollar amount “\$113,894” and add in its place “\$116,766”.

[FR Doc. C1-2019-14101 Filed 10-28-19; 8:45 am]

BILLING CODE 1301-00-D

## DEPARTMENT OF TRANSPORTATION

### Federal Aviation Administration

#### 14 CFR Part 39

[Docket No. FAA-2019-0843; Product Identifier 2019-NE-27-AD; Amendment 39-19777; AD 2019-21-11]

RIN 2120-AA64

#### Airworthiness Directives; Pratt & Whitney Turbofan Engines

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule; request for comments.

**SUMMARY:** The FAA is superseding Airworthiness Directive (AD) 2019-19-11 for certain Pratt & Whitney (PW) PW1519G, PW1521G, PW1521GA, PW1524G, PW1525G, PW1521G-3, PW1524G-3, PW1525G-3, PW1919G, PW1921G, PW1922G, PW1923G, and PW1923G-A model turbofan engines. AD 2019-19-11 required initial and repetitive inspections of the low-pressure compressor (LPC) inlet guide vane (IGV) and the LPC rotor 1 (R1) and, depending on the results of the inspections, possible replacement of the LPC. This AD requires the same inspection of the LPC R1 for cracks or damage, removes the inspection of the LPC IGV for proper alignment, and expands the applicability to certain additional PW turbofan engines. This AD also reduces the compliance time for these inspections for certain PW turbofan engines. This AD was prompted by recent findings of cracks in the LPC R1 and an additional in-flight failure of the LPC R1. The FAA is issuing this AD to address the unsafe condition on these products.

**DATES:** This AD is effective October 29, 2019.

The FAA must receive any comments on this AD by December 13, 2019.

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- *Federal eRulemaking Portal:* Go to <https://www.regulations.gov>. Follow the instructions for submitting comments.

- *Fax:* 202-493-2251.

- *Mail:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590.
- *Hand Delivery:* U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC 20590, between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

For service information identified in this final rule, contact Pratt & Whitney, 400 Main Street, East Hartford, CT 06118; phone: 800-565-0140; fax: 860-565-5442; email: [help24@pw.utc.com](mailto:help24@pw.utc.com); internet: <https://fleetcare.pw.utc.com>. You may view this service information at the FAA, Engine and Propeller Standards Branch, 1200 District Avenue, Burlington, MA 01803. For information on the availability of this material at the FAA, call 781-238-7759. It is also available on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0843.

#### Examining the AD Docket

You may examine the AD docket on the internet at <https://www.regulations.gov> by searching for and locating Docket No. FAA-2019-0843; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this final rule, the regulatory evaluation, any comments received, and other information. The street address for Docket Operations is listed above. Comments will be available in the AD docket shortly after receipt.

**FOR FURTHER INFORMATION CONTACT:** Kevin M. Clark, Aerospace Engineer, ECO Branch, FAA, 1200 District Avenue, Burlington, MA 01803; phone: 781-238-7088; fax: 781-238-7199; email: [kevin.m.clark@faa.gov](mailto:kevin.m.clark@faa.gov).

#### SUPPLEMENTARY INFORMATION:

#### Discussion

The FAA issued AD 2019-19-11, Amendment 39-19747 (84 FR 50719,