

**List of Subjects in 14 CFR Part 39**

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

**Adoption of the Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA amends 14 CFR part 39 as follows:

**PART 39—AIRWORTHINESS DIRECTIVES**

- 1. The authority citation for part 39 continues to read as follows:

**Authority:** 49 U.S.C. 106(g), 40113, 44701.

**§ 39.13 [Amended]**

- 2. The FAA amends § 39.13 by adding the following new airworthiness directive (AD):

**2020–04–11 The Boeing Company:**  
Amendment 39–19850 ; Docket No. FAA–2019–0875; Product Identifier 2019–NM–143–AD.

**(a) Effective Date**

This AD is effective April 13, 2020.

**(b) Affected ADs**

None.

**(c) Applicability**

This AD applies to The Boeing Company Model 747–400 series airplanes, certificated in any category, as identified in Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019.

**(d) Subject**

Air Transport Association (ATA) of America Code 53, Fuselage.

**(e) Unsafe Condition**

This AD was prompted by a report of a certain modification that causes interference with inspections that are intended to detect fatigue cracks. The FAA is issuing this AD to address undetected fatigue cracks, which could result in sudden decompression and loss of structural integrity of the airplane.

**(f) Compliance**

Comply with this AD within the compliance times specified, unless already done.

**(g) Required Actions**

Except as specified by paragraph (h) of this AD: At the applicable times specified in the “Compliance” paragraph of Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019, do all applicable actions identified in, and in accordance with, the Accomplishment Instructions of Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019.

**Note 1 to paragraph (g):** Guidance for accomplishing the actions required by this AD can be found in Boeing Alert Service Bulletin 747–53A2901, dated July 25, 2019, which is referred to in Boeing Alert

Requirements Bulletin 747–53A2901 RB, dated July 25, 2019.

**(h) Exceptions to Service Information Specifications**

(1) For purposes of determining compliance with the requirements of this AD: Where Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019, uses the phrase “the original issue date of the Requirements Bulletin 747–53A2901 RB,” this AD requires using “the effective date of this AD,” except where Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019, uses the phrase “the original issue date of the Requirements Bulletin 747–53A2901 RB” in a note or flag note.

(2) Where Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019, specifies contacting Boeing for repair instructions: This AD requires doing the repair before further flight using a method approved in accordance with the procedures specified in paragraph (i) of this AD.

**(i) Alternative Methods of Compliance (AMOCs)**

(1) The Manager, Seattle ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or local Flight Standards District Office, as appropriate. If sending information directly to the manager of the certification office, send it to the attention of the person identified in paragraph (j) of this AD. Information may be emailed to: [9-ANM-Seattle-ACO-AMOC-Requests@faa.gov](mailto:9-ANM-Seattle-ACO-AMOC-Requests@faa.gov).

(2) Before using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the local flight standards district office/certificate holding district office.

(3) An AMOC that provides an acceptable level of safety may be used for any repair, modification, or alteration required by this AD if it is approved by The Boeing Company Organization Designation Authorization (ODA) that has been authorized by the Manager, Seattle ACO Branch, FAA, to make those findings. To be approved, the repair method, modification deviation, or alteration deviation must meet the certification basis of the airplane, and the approval must specifically refer to this AD.

**(j) Related Information**

For more information about this AD, contact Bill Ashforth, Aerospace Engineer, Airframe Section, FAA, Seattle ACO Branch, 2200 South 216th St., Des Moines, WA 98198; phone and fax: 206–231–3520; email: [bill.ashforth@faa.gov](mailto:bill.ashforth@faa.gov).

**(k) Material Incorporated by Reference**

(1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.

(2) You must use this service information as applicable to do the actions required by this AD, unless the AD specifies otherwise.

(i) Boeing Alert Requirements Bulletin 747–53A2901 RB, dated July 25, 2019.

(ii) [Reserved]

(3) For service information identified in this AD, contact Boeing Commercial Airplanes, Attention: Contractual & Data Services (C&DS), 2600 Westminister Blvd., MC 110–SK57, Seal Beach, CA 90740–5600; telephone 562–797–1717; internet <https://www.myboeingfleet.com>.

(4) You may view this service information at the FAA, Transport Standards Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call 206–231–3195.

(5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov), or go to: <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

Issued on February 20, 2020.

**Gaetano A. Scirtino,**

*Deputy Director for Strategic Initiatives, Compliance & Airworthiness Division, Aircraft Certification Service.*

[FR Doc. 2020–04728 Filed 3–6–20; 8:45 am]

**BILLING CODE 4910–13–P**

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2019–0688; Airspace Docket No. 18–AGL–25]

**RIN 2120–AA66**

**Amendment of VOR Federal Airways V–11 and V–275 in the Vicinity of Bryan, OH, and Defiance, OH, Respectively**

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Final rule.

**SUMMARY:** This action amends VHF Omnidirectional Range (VOR) Federal airways V–11 by redefining the EDGE fix in the vicinity of Bryan, OH, and V–275 by redefining the KLOEE fix in the vicinity of Defiance, OH. These modifications are necessary due to the planned decommissioning of the VOR portion of the Waterville, OH (VWV), VOR/Distance Measuring Equipment (VOR/DME) navigation aid (NAVAID), which provides navigation guidance for portions of the affected air traffic service (ATS) routes. The Waterville VOR is being decommissioned as part of the FAA’s VOR Minimum Operational Network (MON) program.

**DATES:** Effective date 0901 UTC, May 21, 2020. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to

the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11D, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11D at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**FOR FURTHER INFORMATION CONTACT:** Colby Abbott, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267-8783.

#### **SUPPLEMENTARY INFORMATION:**

##### **Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the air traffic service route structure in the National Airspace System as necessary to preserve the safe and efficient flow of air traffic.

##### **History**

The FAA published a notice of proposed rulemaking for Docket No. FAA-2019-0688 in the **Federal Register** (84 FR 52049; October 1, 2019), amending VOR Federal airways V-11 and V-275 due to the planned decommissioning of the VOR portion of the Waterville, OH, VOR/DME NAVAID. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. No comments were received.

VOR Federal airways are published in paragraph 6010(a) of FAA Order 7400.11D dated August 8, 2019, and

effective September 15, 2019, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airways listed in this document will be subsequently published in the Order.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

##### **Availability and Summary of Documents for Incorporation by Reference**

This document amends FAA Order 7400.11D, Airspace Designations and Reporting Points, dated August 8, 2019, and effective September 15, 2019. FAA Order 7400.11D is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11D lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

##### **The Rule**

The FAA is amending Title 14 Code of Federal Regulations (14 CFR) part 71 by modifying VOR Federal airways V-11 and V-275. The planned decommissioning of the Waterville, OH, VOR has made this action necessary. The VOR Federal airway changes are outlined below.

**V-11:** V-11 extends between the Brookley, AL, VORTAC and the intersection of the Fort Wayne, IN, VORTAC 038° and Waterville, OH, VOR/DME 273° radials (EDGE fix). The EDGE fix in the airway description is amended to describe it as the intersection of the existing Fort Wayne VORTAC 038° radial and the Flag City, OH, VORTAC 308° radial. The unaffected portions of the existing airway remain as charted.

**V-275:** V-275 extends between the Cincinnati, KY, VORTAC and the intersection of the Dayton, OH, VOR/DME 007° and the Waterville, OH, VOR/DME 246° radials (KLOEE fix). The KLOEE fix in the airway description is amended to describe it as the intersection of the existing Dayton, OH, VOR/DME 007° radial and the Flag City, OH, VORTAC 313° radial. Additionally, an editorial correction changes the state abbreviation for the Cincinnati VORTAC listed in the description from "OH" to "KY". The unaffected portions of the existing airway remain as charted.

All radials in the route descriptions are stated in True degrees.

##### **Regulatory Notices and Analyses**

The FAA has determined that this proposed regulation only involves an established body of technical regulations for which frequent and routine amendments are necessary to

keep them operationally current. It, therefore: (1) Is not a "significant regulatory action" under Executive Order 12866; (2) is not a "significant rule" under Department of Transportation (DOT) Regulatory Policies and Procedures (44 FR 11034; February 26, 1979); and (3) does not warrant preparation of a regulatory evaluation as the anticipated impact is so minimal. Since this is a routine matter that only affects air traffic procedures and air navigation, it is certified that this rule, when promulgated, does not have a significant economic impact on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

##### **Environmental Review**

The FAA has determined that this airspace action of amending the EDGE fix and KLOEE fix NAVAID radial computations in VOR Federal airways V-61 and V-275, respectively, has no potential to cause any significant environmental impacts, and no extraordinary circumstances exist that warrant preparation of an environmental assessment. Therefore, this airspace action has been categorically excluded from further environmental impact review in accordance with the National Environmental Policy Act (NEPA) and its implementing regulations at 40 CFR parts 1500-1508, and in accordance with FAA Order 1050.1F, Environmental Impacts: Policies and Procedures, paragraph 5-6.5a, which categorically excludes from further environmental impact review rulemaking actions that designate or modify classes of airspace areas, airways, routes, and reporting points (see 14 CFR part 71, Designation of Class A, B, C, D, and E Airspace Areas; Air Traffic Service Routes; and Reporting Points). In accordance with FAA Order 1050.1F, paragraph 5-2 regarding Extraordinary Circumstances, the FAA has reviewed this action for factors and circumstances in which a normally categorically excluded action may have a significant environmental impact requiring further analysis. The FAA has determined no extraordinary circumstances exist that warrant preparation of an environmental assessment or environmental impact study.

##### **List of Subjects in 14 CFR Part 71**

Airspace, Incorporation by reference, Navigation (air).

**The Amendment**

In consideration of the foregoing, the Federal Aviation Administration amends 14 CFR part 71 as follows:

**PART 71—DESIGNATION OF CLASS A, B, C, D, AND E AIRSPACE AREAS; AIR TRAFFIC SERVICE ROUTES; AND REPORTING POINTS**

■ 1. The authority citation for part 71 continues to read as follows:

**Authority:** 49 U.S.C. 106(f), 106(g); 40103, 40113, 40120; E.O. 10854, 24 FR 9565, 3 CFR, 1959–1963 Comp., p. 389.

**§ 71.1 [Amended]**

■ 2. The incorporation by reference in 14 CFR 71.1 of FAA Order 7400.11D, Airspace Designations and Reporting Points, dated August 8, 2019 and effective September 15, 2019, is amended as follows:

*Paragraph 6010(a) Domestic VOR Federal Airways.*

\* \* \* \* \*

**V–11 [Amended]**

From Brookley, AL; Greene County, MS; INT Greene County 315° and Magnolia, MS, 133° radials; Magnolia; Sidon, MS; Holly Springs, MS; Dyersburg, TN; Cunningham, KY; Pocket City, IN; Brickyard, IN; Marion, IN; Fort Wayne, IN; to INT Fort Wayne 038° and Flag City, OH, 308° radials.

\* \* \* \* \*

**V–275 [Amended]**

From Cincinnati, KY; INT Cincinnati 006° and Dayton, OH, 207° radials; Dayton; to INT Dayton 007° and Flag City, OH, 313° radials.

\* \* \* \* \*

Issued in Washington, DC, on March 2, 2020.

**Scott M. Rosenbloom,**

*Acting Manager, Rules and Regulations Group.*

[FR Doc. 2020–04658 Filed 3–6–20; 8:45 am]

**BILLING CODE 4910–13–P**

**ACTION:** Final rule.

**SUMMARY:** This action removes VHF Omnidirectional Range (VOR) Federal airway V–61 in its entirety and extends area navigation (RNAV) route T–286 in its place. The FAA is taking this action due to the planned decommissioning of the Robinson, KS (RBA), VOR portion of the Robinson VOR/Distance Measuring Equipment (VOR/DME) navigation aid (NAVAID). The Robinson VOR is being decommissioned in support of the FAA's VOR Minimum Operational Network (MON) program.

**DATES:** Effective date 0901 UTC, May 21, 2020. The Director of the Federal Register approves this incorporation by reference action under Title 1 Code of Federal Regulations part 51, subject to the annual revision of FAA Order 7400.11 and publication of conforming amendments.

**ADDRESSES:** FAA Order 7400.11D, Airspace Designations and Reporting Points, and subsequent amendments can be viewed online at [https://www.faa.gov/air\\_traffic/publications/](https://www.faa.gov/air_traffic/publications/). For further information, you can contact the Rules and Regulations Group, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783. The Order is also available for inspection at the National Archives and Records Administration (NARA). For information on the availability of FAA Order 7400.11D at NARA, email: [fedreg.legal@nara.gov](mailto:fedreg.legal@nara.gov) or go to <https://www.archives.gov/federal-register/cfr/ibr-locations.html>.

**FOR FURTHER INFORMATION CONTACT:** Colby Abbott, Rules and Regulations Group, Office of Policy, Federal Aviation Administration, 800 Independence Avenue SW, Washington, DC 20591; telephone: (202) 267–8783.

**SUPPLEMENTARY INFORMATION:****Authority for This Rulemaking**

The FAA's authority to issue rules regarding aviation safety is found in Title 49 of the United States Code. Subtitle I, Section 106 describes the authority of the FAA Administrator. Subtitle VII, Aviation Programs, describes in more detail the scope of the agency's authority. This rulemaking is promulgated under the authority described in Subtitle VII, Part A, Subpart I, Section 40103. Under that section, the FAA is charged with prescribing regulations to assign the use of the airspace necessary to ensure the safety of aircraft and the efficient use of airspace. This regulation is within the scope of that authority as it modifies the air traffic service route structure in the

National Airspace System as necessary to preserve the safe and efficient flow of air traffic.

**History**

The FAA published a notice of proposed rulemaking for Docket No. FAA–2019–0677 in the **Federal Register** (84 FR 46905; September 6, 2019) removing VOR Federal airway V–61 and extending RNAV route T–286 in its place. Interested parties were invited to participate in this rulemaking effort by submitting written comments on the proposal. No comments were received.

VOR Federal airways are published in paragraph 6010(a) and RNAV T-routes are published in paragraph 6011 of FAA Order 7400.11D dated August 8, 2019, and effective September 15, 2019, which is incorporated by reference in 14 CFR 71.1. The VOR Federal airway and RNAV T-route listed in this document will be subsequently published in the Order.

FAA Order 7400.11, Airspace Designations and Reporting Points, is published yearly and effective on September 15.

**Availability and Summary of Documents for Incorporation by Reference**

This document amends FAA Order 7400.11D, Airspace Designations and Reporting Points, dated August 8, 2019, and effective September 15, 2019. FAA Order 7400.11D is publicly available as listed in the **ADDRESSES** section of this document. FAA Order 7400.11D lists Class A, B, C, D, and E airspace areas, air traffic service routes, and reporting points.

**The Rule**

The FAA is amending Title 14 Code of Federal Regulations (14 CFR) part 71 by removing VOR Federal airway V–61 and extending RNAV route T–286 to overlay the V–61 routing being removed. The planned decommissioning of the VOR portion of the Robinson, KS, VOR/DME has made this action necessary. The air traffic service (ATS) route actions are described below.

**V–61:** V–61 extends between the Grand Island, NE, VOR/DME and the intersection of the Robinson, KS, VOR/DME 141° and St. Joseph, MO, VOR Tactical Air Navigation (VORTAC) 211° radials (BOWLR fix). The airway is removed in its entirety.

**T–286:** T–286 extends between the Rapid City, SD, VORTAC and the Grand Island, NE, VOR/DME. The route is extended southeast between the Grand Island VOR/DME and the BOWLR fix. Additionally, the Rapid City VORTAC

**DEPARTMENT OF TRANSPORTATION****Federal Aviation Administration****14 CFR Part 71**

[Docket No. FAA–2019–0677; Airspace Docket No. 19–ACE–5]

**RIN 2120–AA66**

**Revocation of VHF Omnidirectional Range (VOR) Federal Airway V–61 and Amendment of Area Navigation Route T–286 Due to the Decommissioning of the Robinson, KS, VOR**

**AGENCY:** Federal Aviation Administration (FAA), DOT.